



1.13


Quantitative

Std. Familiarization Time: 0:15:00

Approximate Video Time: 0:11:00

[Play the Video](#)

Batch-at-a-Glance



Calibration Curve Pane (1/2)

- Single Calibration Curve and Twelve Calibration Curve
- Color of the calibration curve level point
- How to ignore a calibration curve level
- How to change the calibration curve type
- Changing the origin of the calibration curve
- Changing the weighting of the calibration curve

Calibration Curve Pane (2/2)

- Changing the ISTD of the calibration curve
- Changing the calibration curve level
- Printing calibration curve data
- Exporting the table in the batch table pane
- Exporting graphics